

Town Of Marion

Department of Public Works Operations Center April 6, 2022











State of Current Facility:















Why New Facility is Needed:

- Current facilities sub-standard, do not meet DPW operational needs
- Staff break, locker, shop areas below a reasonable standard
- Current buildings do not meet OSHA / Safety Standards
- Limitations in storing and properly maintaining significant capital equipment owned by town
- MS4 requires covered salt/sand storage




























First Floor Plan

First Floor Area: 3,569 S.F. Loft Area: 959 S.F. Total Area: 4,528 S.F.






































- 52' x 60' Structure, 1,500 ton capacity
- Precast Block Foundation
- Galvanized Frame
- Heavy Duty Fabric Enclosure





Targeted Sustainable Strategies:

- Potential 5,450 sq.ft. roof area on Operations Center and Covered Parking Structure for solar photovoltaic installation
- Durable pre-engineered metal building structures
- High-efficiency building envelope and systems
- Site development strategy that takes advantage of existing utility infrastructure, parking inventory, and stormwater management systems





Marion DPW Operations Center	
Estimated Total Project Cost	\$4,456,155
Funding Sources	
Free Cash	\$1,500,000
Borrowing	\$3,000,000

